



2305 Larkspur Ln.  
Redding, CA 96002

# Repair Estimate

Date	Estimate #
4/5/2023	1330

Name / Address
BURNEY WATER DISTRICT 2022 HUDSON STREET BURNEY, CA 96013

Service Address

WE PROPOSE TO FURNISH LABOR AND MATERIAL IN STRICT ACCORDANCE WITH THE PLANS AND/OR SPECIFICATIONS AS FOLLOWS:

Rep	GATE COMBO	Project
		SERVICE-POOL

Description	Qty	Rate	Total
TO REPAIR HEATER			
ORIFICES	28	16.08	450.24T
HEAT EXCHANGER	1	12,531.09	12,531.09T
HEADER GASKETS	2	97.93	195.86T
FLANGE GASKETS	2	42.22	84.44T
WATER BARRIER GASKET	1	25.12	25.12T
FREIGHT CHARGES		785.00	785.00
TRAVEL FEE		600.00	600.00
SERVICE LABOR	1	2,700.00	2,700.00
ESTIMATE IS BASED OFF OF A TYPICAL INSTALLATION. LABOR MAY CHANGE ONCE WORK HAS STARTED. THE TECHNICIAN WILL BE IN CONTACT WITH YOU ABOUT ANY CHANGES.			
CALIFORNIA SALES TAX		7.25%	963.29

**\*\*a 10% deposit and signature of approval on this estimate sheet prior to parts being ordered.**  
**\*\*Final payment is due upon completion of work.**  
**\*\*If work is done in addition to the items listed above, prices will change accordingly. This estimate expires 30 days after the date of this estimate.**  
**\*\*If the work is cancelled after equipment/parts are ordered, you will be charged a 25% restocking fee.**

<b>Total</b>	<b>\$18,335.04</b>
--------------	--------------------