To: Burney Water District Board of Directors

From: David Zevely, District Manager

Date: March 16, 2023

Subject: District Manager's Report, Summary of Activities from February 15 to March 16, 2023

## **February**

• Submitted January 2023 drinking water monthly report to SWRCB staff for review.

- Staff started the California Professional Excavator training webinar that covers state laws, codes, and regulations; industry best practices; and the 811 process for safe excavation.
- Well 7 pump failed to run when called by SCADA. BAT electric was called and repaired a faulty relay.
- Staff attended a monthly construction meeting with PACE Engineers and RTA Construction to discuss recent and future work at the WWTP and collection system.
- Staff spoke with Shasta College Water Treatment Technology teacher about Operator-In-Training opportunities for students.

## WWTP and Collection System Improvement Projects

The weather has caused a slowdown in work, so not as many tasks have been completed in the past month. Below is the summary of major tasks worked on since last reported:

Collection System Major Tasks:

1. None

WWTP Major Tasks Worked On:

- Conduit trenching and installation around Control building and treatment facilities.
- 2. WDS Line trenching (including rock excavation and disposal) and installation.

#### March

- Reported to the online portal, CIWQS, a collection system spill for February 2023, 10-gallons spilled from a sewer lateral clean out. Approximately 8-gallons was recovered from the spill, and the spill site was cleaned up.
- Submitted January 2023 Wastewater treatment plant report to SWRCB staff for review.
- Keith Moore and David Zevely registered for a Backflow Tester certification course. The training is **postponed to May 21-27, 2023,** Due to unforeseen instructor circumstances. The training is held at the Cal Rural Water Association training center, Sacramento.
- Staff noticed sludge was not settling as expected at the plant. Staff repeated the prescribed RAS chlorination procedure to improve settling/control filamentous bacteria. Sludge settling improved after a few days of chlorination. Staff stopped chlorinating and is keeping a close eye on sludge settling.
- Willie Lyons, Utility Worker, resigned from the District.
- District staff placed a job flyer on the District website, on the CWEA website job listings, on North State Jobs website, and with the Intermountain Area Jobs on the March job listings.

### Field Operations

In February, Field staff

- Repaired a 6-inch failed water main on Clusterwood Court That was causing a significant water leak.
- Dug up a frozen water main on Bue Way and was able to thaw the main and re-establish water service to a residence.
- Ordered a custom fabricated debris bin for the WWTP headworks hopper to help reduce/eliminate overflowing of current debris bins at the WWTP static screen building.
- Addressed multiple meter box leaks, a sewer plug, and nuisance alarm calls that occurred in February.
- Maintained treatment plant equipment, adjusted plant processes, grabbed permit-required and process samples, and maintained plant grounds. Pace Analytical in Redding, CA, analyzed permit-required samples and provided laboratory analytical results. Staff evaluated process sample results and used results to adjust equipment and wastewater treatment processes.
- Grabbed monthly water system routine samples and those were tested by Pace Analytical laboratory in Redding and submitted to the State.
- Marked underground service alerts throughout the month.

# Service Requests and Call Outs

In February, during business hours, staff responded to the following number of water and sewer service requests:

- 3 Water turn on requests
- 8 Water turn off requests
- 14 Meter re-reads and final reads (moving)
- 2 Sewer service request (backups on either customer or District side)
- 13 Water maintenance requests (leaky valves, broken lines, pressure checks)
- 3 Water meter replacement- related tags

In February, staff responded to 15 after-hour calls for the following:

- Telemetry alarm at a water tank
- Water leak on main line at Clusterwood Court
- Repair frozen service line on Bue Way (6)
- WWTP alarm from California Safety
- Well 7 pump relay failure (2)
- Leaking fire hydrant
- Sewer backup on customer side
- Hi-level alarm at the main lift station during rain event
- Autodialer power failure alarm